

		<b>TOYOTA</b>		<b>ECR #:06-097</b>	
		Toyota Motor Sales, U.S.A., Inc.		Type <input checked="" type="radio"/> TMS <input type="radio"/> Supplier	
		<b>Genuine Accessories</b>		<b>COST EFFECT:</b> <input checked="" type="radio"/> + <input type="radio"/> <b>\$500.000</b>	
		<b>Engineering Change Request</b>			
Current Part No.: PT908-21050-02		New Part No.: PT908-21051-02		Current Part # <input checked="" type="radio"/> Retain <input type="radio"/> Cancel	
Part Name:	Floor Mats	Vehicle: Prius		MY: 2006	
Part Description:	All Weather Mat Kit- Black	Other vehicle info.:			
<b>Reason for Change:</b> Reduce height or border around accelerator pedal to reduce risk of pedal interfering with mat. Current design already has adequate clearance between mat and accelerator pedal. The new design will be better in cases where the customer does not properly install the driver's mat with the retention clip.					
<b>Change Description:</b> Driver's mat: Terminate border on the vertical (in-board) edge, in-line with the top of the heel pad.  Border will no longer be on the horizontal edge below accelerator pedal.					
Interchangeability Affected?	<input type="radio"/> Yes <input checked="" type="radio"/> No	Drawing Affected	<input checked="" type="radio"/> Yes <input type="radio"/> No	Sample Date:	Effective Date:
Company Name:	Thermoflex				
<b>TMS Comments:</b> The current parts (PT908-21050-02) should all be used up prior to offering the new part numbers to the dealers. The two part numbers are interchangeable.					
<b>Thermoflex needs to update:</b> - Drawings - BOM					
Approver Comments entered below :				Part Disposition	
Buyer:	To change tool = \$500; If can not change tool, we will need new tool = \$12,000. Supplier has strongly advised they believe they can modify tooling.			<input checked="" type="radio"/> Use <input type="radio"/> Scrap <input type="radio"/> Return <input type="radio"/> Other	
<b>TOTAL COST DATA</b>	<b>CURRENT</b>	<b>CHANGE</b>	<b>NEW</b>		
FOB	\$24.35				
Cost (numeric)					
<b>DEVELOPMENT</b>	\$0.00				
Cost (numeric)					
<b>TOOLING</b>	\$500.00			Attach ISIR Checklist File Here	
Cost (numeric)					
Quality:					
Development Manager:					
<b>Supplier Comments:</b>					
<b>Distribution as Required</b>					
<b>Standard Distribution</b>	<input checked="" type="radio"/> Accessory Dev. - Group 1 <input type="radio"/> Accessory Dev. - Group 3 <input type="radio"/> Accessory Dev. - Group 2 <input type="radio"/> Accessory Dev. - Group 4		Jacob Hoffman, Elsa Alvarez, Ken Tran, Tyrone Taketa, Daniel Fragoso, Douglas Yamamoto		

02-CAD-E-100 (JMH - 08/19/2005)

ECR

Request ID KRAE-6QMTMTA

Requested By

Ketan Ranade

Request Date

06/19/2006 04:36:51 PM

Status


Complete



Requester

Ketan Ranade

Approvers



Toni Blakeman

Wes Migletz

Blane Marosek